




HM-50 Heavy Metal Pedal

174.207UK



Functions

1. D.C. In – DC jack for optional mains adapter
2. Indicator LED – Shows when effect is on (when it appears dim, replace battery)
3. LEVEL – Adjusts the output level
4. LOW – Adjusts the low frequency content of the distorted effect
5. HIGH – Adjusts the high frequency content of the distorted effect
6. MIDDLE – Adjusts the middle frequency content of the distorted effect
7. MID FREQ – Sets the frequency range at which the MIDDLE control operates
8. Pedal Switch – Turns Effect On/Off
9. Input – 6.3mm mono jack connector
10. Battery housing – Compartment underneath for 9V battery
11. Output – 6.3mm mono jack connector
12. DIST – Adjusts the level of distortion and sustain applied to the signal

Notes on use

- Connecting to the Input jack enables the battery, please disconnect when not in use to preserve the battery
- Before connecting to an instrument, ensure amplifier volume is turned down

Specifications

- Input Impedance: 1M Ω
- Output Impedance: 1k Ω
- Power Supply: 9Vdc (battery or optional mains adapter) 18mA

